

TROUBLESHOOTING for CK2555 & CK2575

AIR TRAP

A common problem, that our customers report, is due to poor maintenance of the air trap.

The air trap is located on the back wall inside the washing chamber (Pic 1). A build up of dirt behind the plastic protection means the machine will stop filling. (Pic 2)

This problem ISN'T covered by our warranty due to lack of maintenance.

To solve the problem simply remove the 2 metal nuts (Pic 3), give the area a quick wipe and replace (Pic 4). This only needs completing monthly.



Pic 1



Pic 2



Pic 3



Pic 4